



Corneal Staining




Causes:
Flat Fit – Increase Sag

Well Centred – Lens
binding, deposits,
manufacturing error




Causes:
Inferior – Steep fit,
Bound Lens, Flat fit

Superior – Flat fit



Causes:
Steep Fit – Too much
clearance

Optimal Fit – Lens
insertion



Causes:
Poor Fit

Increased Tear
Viscosity

Heavily Deposited
Lenses