



Sterilising STEPPER Frames and Sunglasses

Coronavirus requires all of us to eliminate the possibility of cross-contamination.

The handling and trying on of frames have always been an integral part of our daily working life. This presents new challenges for our businesses.

STEPPER recommends you adopt strict sterilisation methods in your working practice as follows:

-Clean frames after every use, rather than a once-a-week deep clean using:

UVC Chamber

Washing:

- By hand in soap & water
- In an ultrasonic bath containing soapy water

Using a UVC Chamber

Use a germicidal lamp with between 200 and 280 nm ultraviolet rays, these instruments quickly eliminate any microorganism.



This is an example of a UVC chamber. A number of STEPPER businesses have already sourced these from Centrostyle within the countries which they operate.

Washing Recommendations

Use soap and hot water to rinse the germs away.

Dry frames after cleaning. Use disposable cloths or paper towels when possible (reusable cloths should be disinfected or washed at 60C [140F] after each use)

Stay safe.

A handwritten signature in black ink, which appears to read 'Hans Stepper', is written in a cursive style.

Hans Stepper